

STATE OF TEXAS WELL REPORT for Tracking #458827

Owner: **Ismael Marquez** Owner Well #: **No Data**
Address: **1374 S. War Admiral
Odessa , TX 79764** Grid #: **45-12-8**
Well Location: **1374 S. War Admiral
Odessa, TX 79764** Latitude: **31° 47' 21.1" N**
Longitude: **102° 32' 55.14" W**
Well County: **Ector** Elevation: **No Data**
****Plugged Within 48 Hours****

****This well has been plugged****

Plugging Report Tracking #171008

Type of Work: **New Well**

Proposed Use: **Irrigation**

Drilling Start Date: **8/23/2017** Drilling End Date: **8/23/2017**

	<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
Borehole:	7.78	0	170

Drilling Method: **Air Rotary**

Borehole Completion: **Plugged**

	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks & material)</i>
Annular Seal Data:	0	10	Cement 2 Bags/Sacks
	10	170	Back Fill & Hole Plug 1 Bags/Sacks

Seal Method: **Hand Mixed**

Distance to Property Line (ft.): **No Data**

Sealed By: **Driller**

Distance to Septic Field or other
concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: **No Data**

Surface Completion by Driller

Water Level: **No Data on 2017-08-23**

Measurement Method: **Sonic/Radar**

Packers: **No Data**

Type of Pump: **No Data**

Well Tests: **Estimated** Yield: **0 GPM**

	<i>Description (number of sacks & material)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
Plug Information:	Back Fill & Hole Plug & Cement	0	170

Water Quality:

Strata Depth (ft.)	Water Type
0 - 0	No Data

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which
contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **MARK'S WATER WELL SERVICE, INC**
PO BOX 295
ODESSA, TX 79763

Driller Name: **Bryan A Mehlhoff** License Number: **59300**

Comments: **No Data**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing:
BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description
0	60	Rock & Caliche
60	80	Caliche & Brown Sand Stone
80	100	Brown Sand Stone
100	120	Brown Sand Stone & Brown Sand
120	140	Brown Sand & Yellow Sand
140	160	Yellow Sand & White Sand
160	170	White Sand & Red Bed

Dia. (in.)	New/Used	Type	Setting From/To (ft.)
No Data			

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540